

# SECOND REPORT ON POST-EARTHQUAKE INVESTIGATION, WEWAK

Hugh Davies, UPNG  
September 20, 2002

## OBJECTIVES

The visit was undertaken with the following objectives:

1. confirm the uplift of the Wewak islands; and
2. examine earthquake and tsunami damage at localities that were not seen on first visit. After discussion on 18 September in Wewak, three other objectives were added:
3. check any evidence for volcanic activity in Victoria Bay or elsewhere;
4. check reports of a possible major fault or impending major slope failure on the north side of Kairiru Island; and
5. discuss with the public the aftershocks that had occurred since the M7.6 earthquake of 9.9.02.

## SUMMARY OF RESULTS

### 1. UPLIFT

Most of the islands have been elevated by 30–40 cm (vertical distance). The uplift shows on the shorelines of Tarawai, Walis, Kairiru and the part of Mushu that was visited (northwest Mushu). The uplift is expressed in the emergence of reefs and wave-cut platforms, in the development of a new high-water mark on beaches, in the drying out of near-shore sea-grass banks that are now exposed at medium and low tide, and the drying out of swamps, and the (reported) lowering of the water table in open wells.

### 2. IMPLICATION OF THE UPLIFT FOR FOOD CROPS

The drying out of swamps on the islands, if long lasting, can have serious implications for food supply, because of the reduced growth of sago palm, and the lack of the plentiful supply of fresh water needed to process sago. Garden crops such as sweet potato, yams and greens, also could be affected if the soil becomes drier as a result of the lower water table. This effect can be exacerbated by the predicted low rainfall in the next year or so, due to the current El Niño conditions.

### 3. DAMAGE CAUSED BY THE TSUNAMI

Most of the damage on the morning of 9.9.02 was caused by the earthquake and not by the moderate tsunami that followed. Damage caused by the tsunami is known at three locations. No person is known to have been injured by the tsunami. One location is Buruwan in Victoria Bay, Kairiru Island, where a tsunami wave approached the shoreline obliquely from the southwest, as it swirled anti-clockwise along the shore of the bay. Run-up height exceeded 3 m, and inundation reached 50 m inland. The wave carried large logs into the front of the village, where one house collapsed and another was damaged. Villagers were alerted to the approach of the wave by a lone fisherman, who had gone to the beach. None was hurt. Two other fishermen observed the wave from their canoes some hundreds of metres out to sea.

Another locality is Boiken, on the mainland, where a house was swept inland by a wave with run-up height of 3–4 m (information from Bishop Anthony Burgess). On the north coast of Mushu Island, opposite St Xavier's School, a house was swept towards the sea by the returning waters, after a tsunami wave had swept inland; and there are reports that houses were swept into the sea by a tsunami wave on the south coast of Mushu Island. None of these localities was visited by the writer.

### 4. MATERIALS FOR RE-BUILDING HOUSES

Some hundreds of houses were destroyed by the earthquake and are to be rebuilt. The communities are self-reliant and are already cleaning up and rebuilding. Some but not all of the building materials from the former houses can be salvaged and re-used. Depending on how much material can be recycled, there will be a need for new materials, including morata roofing, nails, Kanda vine rope, and timber. For some communities, notably on the smaller islands such as Tarawai, where there are limited areas of forest and swamp, bush materials such as timber and morata are not readily available. Assistance from outside sources may be needed if houses are to be rebuilt before the onset of the Northwest Monsoon in December–January.

### 5. RUMOURS OF IMPENDING VOLCANIC ERUPTION

On 18 September, rumours of an impending volcanic eruption were circulating in Wewak and the Wewak area, and were causing concern and fear amongst the general public. Various reports were that the hot springs in Victoria Bay had shut down and so were building up to an explosion, or that Kairiru mountain itself might erupt. The published geological map shows that Kairiru, although composed mostly of volcanic rock, is not an active or dormant volcano but is, rather, a pile of 30-million-year old volcanic rock and sediment – rocks that have been folded and faulted and eroded, and show no indication of further volcanic activity.

With the object of confirming that the previous mapping was correct, observations of coastal rock outcrops were made in and near Victoria Bay along the north coast. The outcrops are of rocks from the core of a volcanic complex that had been deeply eroded. There were no volcanic rocks of modern origin, and no indication of recent volcanic activity, and no indication that volcanic activity was likely to develop. Contrary to rumour, the main hot spring in Victoria Bay, at Wai, was seen to be flowing vigorously. Nearby several new small hot springs had developed. Hot springs develop where water that has been heated deep in the earth can reach the surface, travelling along fractures in the rock. The hot springs on Kairiru have been known for many years, and are not an indication of impending volcanic activity.

Conclusion: The rocks in Victoria Bay clearly are not part of a modern active volcano and there is absolutely no evidence that a volcano is going to develop in Victoria Bay or at any other point in the Wewak islands.

## 6. SLOPE FAILURES ON THE NORTH COAST OF KAIRIRU

Villagers on the north coast of Kairiru Island had noted cracks in the ground upslope from Bou Primary School, Korgur (Kragur) and Shagur, and possibly extending further west to Rumlal and Surai. There was concern that the cracks might be interconnected and might be the surface expression of a deep-seated fault or zone of weakness in the earth's crust that could fail catastrophically. There was speculation that entire hillsides and villages might be at risk.

An inspection by helicopter revealed that there are a great many fresh landslides on the northern slopes of Kairiru Island, especially in the east, where weaker sedimentary rocks are exposed. An inspection on the ground of the steep slopes behind Korgur (Kragur) confirmed that there are many cracks in the ground, some showing downslope displacement of 20–30 cm. It was clear that in each case the cracks were caused by incipient small-scale slope failure, and were the combined result of over-steepening of the ridge slopes by erosion, and of shaking by the earthquake. Each of the cracks clearly is local, and extends to a relatively shallow depth. In time, some of the cracks may develop into landslides. The landslides are likely to be on a relatively small scale, such as the village people are accustomed to. There is no evidence of a deep-seated zone of weakness, and no evidence that there will be any massive large-scale failure of the northern slopes.

## 7. POSSIBLE DANGER FROM LANDSLIDES ON KAIRIRU

Many new landslides developed, or old landslides were re-activated, at the time of the earthquake of 9.9.02. Some of these landslides may represent a threat to the safety of people and gardens below. The most extensive landslides are on the eastern slopes of Kairiru, and towards the eastern end of the northern slopes, above Baru, where the slopes are made up of weaker rocks. These areas should be examined by an engineering geologist to determine whether any threat to safety exists. Another locality that needs to be examined is the high vertical face exposed by a landslide southwest of Rumlal, at the western end of the north slopes of the island. This may be unstable and may pose a threat to homes and gardens.

## 8. AFTERSHOCKS

In the period of this visit, 18–20 September, one or more aftershocks occurred each day. The continuing tremors were adding to the tension and fear in the community. The people were advised that aftershocks are to be expected after any major earthquake, and may be expected to continue for some months. They also were advised that aftershocks are normally weaker than the original earthquake, but can be strong enough to trigger a tsunami, so they should continue to observe tsunami safety procedures at the time of any strongly felt earthquake.

## 9. FURTHER INVESTIGATIONS

A team of three tsunami scientists from the United States will be in Wewak 25–30 September to continue the mapping and recording of the traces of the tsunami. The team comprises Dr Jose Borrero and Mr Burak Uslu of the University of Southern California, and Dr John Freckman of the ports authority of the State of California. They will be accompanied by a senior geology student from University of PNG, Mr James Bu, and will be assisted in Wewak by Mr Pius Mukanje of the Wewak Provincial Disaster Committee. The team will report their findings to the Provincial and National authorities. They also will

present a computer to the University of PNG with the software needed for computer modeling of tsunamis, and will conduct a training session, so that this type of research can be conducted in PNG.

Hugh Davies  
Professor of Geology  
UNIVERSITY OF PAPUA NEW GUINEA  
Email [hdavies@upng.ac.pg](mailto:hdavies@upng.ac.pg)  
Telephone 3267173, 36267395, 3260268  
Fax 3260369